

REPLACE DAMAGED COLD STORAGE FLOORING

INDUSTRY	Mining
CLIENT	Dugal River Mine
DISTRIBUTOR	ShieldCrete Australia 1800 364 776 www.shieldcreteinternational.com
APPLICATOR	Spillers QCC
PROJECT	Replace damaged linoleum flooring and provide easy-clean non-slip floor.
LOCATION	QLD, Australia
COATING SYSTEM	2mm ShieldPoly F-15 over ShieldPrime UNI primer.
DATE	2018

Description

The client's freezer floor was constantly being damaged from the regular movement and cleaning, particularly at the door. They contacted Spillers QCC who suggested Polyurea as the most appropriate solution.

Once on site and the flooring was exposed, it was noted that there was significant water/ice damage to the floor panels. The panels were replaced, and the coating applied.

The coating was finished with a dry-fall application technique to give slip resistance and ease of cleaning.

Against all advice, the customer used a moisture absorbing floor material for the repairs. Despite the decision, they have had years of good service from the polyurea as it is unaffected by the cold temperatures and the traffic.

